

BELIZE DEPARTMENT OF CIVIL AVIATION

Aircraft Accident Investigation Unit (AAIU)



INTERIM STATEMENT

Date:	1 April, 2022
Time:	5:00 local time
Location of the occurrence:	Philip SW Goldson International Airport
Latitude/longitude:	N 17° 32' 21" W 088° 18' 30"
Aircraft (Make/Model):	Embraer 110PL - Bandeirante
Registration:	TG-TAN
Operator:	TAG Airlines
Category of the occurrence:	Accident
Involved States:	Guatemala, Belize, Brazil

1. History of the flight

On 1 April 2022, TG-TAN, Embraer 110-PL, TAG Airlines (Transportes Aereos Guatemaltecos) was involved in an accident at the Philip SW Goldson International Airport at approximately 5:00 pm local time. While on departure the aircraft sustained significant damages to both propeller during the take-off phase. This was due to both propellers striking the runway surface and causing instability of the aircraft.

2. Investigation activities conducted.

Landing gear system test was carried out
Medical examinations were conducted
Interviews were conducted with both flight crew

3. Conclusions

The landing gear system was working satisfactorily during the test.

4. Recommendations already issued.

In draft final report

5. Next steps

- a) Review and approval of draft final report
- b) Send approval draft final report to relevant States
- c) Approval and completion of final report

6. Additional comments

None